NEPR

Received:

Sep 23, 2022

2:51 PM

## GOVERNMENT OF PUERTO RICO PUERTO RICO PUBLIC SERVICE REGULATORY BOARD PUERTO RICO ENERGY BUREAU

IN RE: INTERRUPCIÓN DE SERVICIO ELÉCTRICO DE 6 DE ABRIL DE 2022

CASE NO. NEPR-IN-2022-0002

**SUBJECT:** 

Informative Motion on Submittal of Root Cause Analysis

## INFORMATIVE MOTION ON SUBMITTAL OF ROOT CAUSE ANALYSIS

## TO THE HONORABLE PUERTO RICO ENERGY BUREAU:

COME now LUMA Energy, LLC ("ManagementCo") and LUMA Energy ServCo, LLC ("ServCo") (jointly referred to as the "Operator" or "LUMA"), and respectfully state and request the following<sup>1</sup>:

- 1. On April 6<sup>th</sup> 2022, a failure in the electric system led to a fire at the Costa Sur transmission substation, which resulted in a power outage of the entire electrical system (hereinafter, the "April 6<sup>th</sup> Incident").
- 2. On April 8<sup>th</sup> 2022, this Honorable Puerto Rico Energy Bureau ("Energy Bureau") issued a Resolution and Order whereby it initiated an investigation of the April 6<sup>th</sup> Incident ("April 8<sup>th</sup> Order").
- 3. On April 12<sup>th</sup>, 2022, in compliance with the April 8<sup>th</sup> Order, LUMA submitted the Preliminary Report of the April 6<sup>th</sup> Incident. The Preliminary Report included the information that

<sup>&</sup>lt;sup>1</sup> Capitalized terms not defined herein shall have the meaning ascribed to them in LUMA's *Motion Submitting Updated Report and Request for Confidential Treatment*, filed in this Energy Bureau on April 18<sup>th</sup>, 2022.

LUMA had gathered thus far, preliminary findings and assessments of the April 6<sup>th</sup> Incident, and a summary of the corrective actions taken by LUMA.

- 4. On April 14<sup>th</sup>, 2022, to aid the Energy Bureau in its investigation and supplement the Preliminary Report, LUMA filed a *Motion to Supplement Preliminary Report on April 6<sup>th</sup> Incident*. Therein, LUMA submitted two (2) video recordings, including a screen recording from the Costa Sur transmission substation that shows a few minutes before and after the failure of oil circuit breaker number 0082 at the Costa Sur Substation's 230kV switchyard on April 6th, and an aerial view video of the Costa Sur Substation taken the morning after the April 6<sup>th</sup> Incident.
- 5. On April 18<sup>th</sup>, 2022, in compliance with the April 8<sup>th</sup> Order and to be transparent with its customers and regulators about its operations, LUMA filed a *Motion Submitting Updated Report and Request for Confidential Treatment*. Therein, LUMA submitted the Updated Report of the April 6th Incident, which provided an update on the following topics:
  - i. Overview of third-party industry expert hired to assist with analysis;
  - ii. Outage investigation update and proactive maintenance plan/strategy;
  - iii. System analysis update including adding dynamic stability analysis into model; and
  - iv. Ongoing restoration activities at Costa Sur.
- 6. On April 22<sup>nd</sup>, 2022, the Energy Bureau issued a Resolution and Order instructing LUMA and PREPA to submit, on or before May 6<sup>th</sup>, 2022, at noon, certain documents and information in connection with the April 6th Incident ("April 22<sup>nd</sup> Order").
- 7. On May 9<sup>th</sup>, 2022, LUMA submitted all documents and information in its possession, custody, and control, which were responsive to the Energy Bureau's requests for documents and information. They included a sworn statement signed by Darrell Wilvers, LUMA's

Director of Asset Management, stating that the documents produced were exact copies of the original documents and that the information provided was true and correct. Further, LUMA also submitted a Second Updated Report of the April 6<sup>th</sup> Incident, which provided an update on the schedule and status of the investigation.

- 8. In the Second Updated Report of the April 6<sup>th</sup> Incident, LUMA informed the Energy Bureau that the remaining elements of the investigation schedule included a Root Cause Analysis that would be submitted on or before September 23, 2022.
- 9. LUMA has been working diligently to finalize the Root Cause Report Analysis. However, the unforeseen event beyond LUMA's control of the passage through Puerto Rico of Hurricane Fiona on September 18, 2022, required the deployment of LUMA's workforce to prepare for and address an island-wide emergency, resulting in an unforeseen delay in gathering the information needed to finalize the report. Due to these circumstances, LUMA needs additional time to submit the report. As this Energy Bureau has been made aware, the April 6<sup>th</sup> Incident is part of an ongoing investigation to which the pertinent LUMA employees devote a substantial effort. In view of the aforementioned, LUMA respectfully informs the Energy Bureau that it will submit the Root Cause Analysis on or before October 7, 2022.

**WHEREFORE,** LUMA respectfully requests that the Energy Bureau **take notice** of the aforementioned.

## RESPECTFULLY SUBMITTED.

We hereby certify that we filed this motion using the electronic filing system of this Energy Bureau and that we will send an electronic copy of this motion to the attorney for PREPA, Bolaños-Lugo, kbolanos@diazvaz.law.

In San Juan, Puerto Rico, this 23<sup>rd</sup> day of September 2022.



**DLA Piper (Puerto Rico) LLC** 500 Calle de la Tanca, Suite 401

San Juan, PR 00901-1969 Tel. 787-945-9107/ 9132 Fax 939-697-6147/ 6102

/s/ Yahaira De la Rosa Algarín Yahaira De la Rosa Algarín RUA NÚM. 18,061 yahaira.delarosa@us.dlapiper.com

/s/ Iván Garau-González Iván Garau-González RUA NÚM. 20,229 ivan.garau@us.dlapiper.com